HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

John Breuner and Company Building 1515 Clay Street Oakland Alameda County California

HABS No. CA-2296

Jack Schafer, Photographer

November 1990

CA-2296-1 FACING WEST ALONG 15TH STREET FROM SAN PABLO AVENUE. CITY HALL PLAZA, OAKLAND CITY HALL AND SURROUNDING COMMERCIAL BUILDINGS IN FOREGROUND, JOHN BREUNER AND COMPANY BUILDING IN BACKGROUND.

CA-2296-2 FACING WEST ALONG 15TH STREET, SHOWING BUILDINGS ALONG NORTH SIDE OF 15TH STREET, FROM LEFT TO RIGHT: CLARIDGE APARTMENTS (BACKGROUND), JOHN BREUNER AND COMPANY BUILDING, DALZIEL BUILDING, AND THE PLAZA

BUILDING. CITY HALL PARK IN FOREGROUND.

CA-2296-3 FACING WEST-NORTHWEST ALONG 15TH STREET SHOWING BUILDINGS ON NORTH SIDE OF 15TH STREET. JOHN BREUNER AND COMPANY BUILDING SOUTH SIDE AND EAST FRONT.

CA-2296-4 FACING SOUTH AT JEFFERSON STREET AND 16TH STREET. NORTH AND WEST BACKSIDES OF JOHN BREUNER AND COMPANY BUILDING IN CENTER (BACKGROUND), SURROUNDING

STRUCTURES ON CLAY, JEFFERSON AND 15TH STREETS AT LEFT,

RIGHT, AND FOREGROUND.

CA-2296-5 OVERALL VIEW OF JOHN BREUNER AND COMPANY BUILDING,

SOUTH SIDE AND EAST FRONT, FACING NORTHWEST. ANNEX

AT LEFT.

FACING NORTH ALONG CLAY STREET, SHOWING BUILDINGS ON CA-2296-6

THE WEST SIDE OF CLAY STREET, FROM LEFT TO RIGHT: JOHN BREUNER AND COMPANY BUILDING (FOREGROUND), HOTEL TOURAINE (MIDDLE), AND THE PACIFIC GAS AND ELECTRIC CO.

BUILDING.

(continued)

John Breuner and Company Bldg. HABS No. CA-2296 (Page 2) Index to Photographs

CA-2296-7	DETAIL OF GROUND, MEZZANINE, AND FIRST FLOOR WINDOW OPENINGS AT CORNER OF CLAY AND 15TH STREETS. WINDOWS AND WINDOW FRAMES REMOVED.
CA-2296-8	DETAIL OF EIGHTH (TOP) FLOOR AT CLAY AND 15TH STREETS SHOWING ORNAMENTAL TERRA COTTA BANDING AND RELIEF PANELS. WINDOWS, WINDOW FRAMES, AND METAL CORNICE REMOVED.
CA-2296-9	DETAIL OF ORNAMENTAL TERRA COTTA FRIEZE ABOVE GROUND FLOOR AND TYPICAL TERRA COTTA WINDOW SILL. CORNER OF CLAY AND 15TH STREETS.
CA-2296-10	INTERIOR VIEW ON MEZZANINE ALONG EAST (CLAY STREET) FRONT FACING OAKLAND CITY HALL. TYPICAL INTERIOR CONDITIONS OF PARTIAL DEMOLITION; WINDOWS, WINDOW FRAMES, SUSPENDED CEILING, AND MOVABLE PARTITION WALLS REMOVED.
CA-2296-11	INTERIOR VIEW ON SEVENTH FLOOR ALONG EAST (CLAY STREET) FRONT. TYPICAL INTERIOR CONDITIONS OF PARTIAL DEMOLITION; SUSPENDED CEILING AND MOVABLE PARTITION WALLS REMOVED, REMAINS OF DEMOLISHED SHEET METAL CORNICE FROM BUILDING EXTERIOR VISIBLE ON FLOOR.
CA-2296-12	INTERIOR VIEW ON SEVENTH FLOOR AT CORNER OF CLAY AND 15TH STREETS. LARGE SECTIONS OF DEMOLISHED SHEET METAL CORNICE FROM BUILDING EXTERIOR VISIBLE IN FOREGROUND.